



NB. for detailed information please refer to OEM wiring schematic



Colour Coded Wiring Loom Installation Plan

Replaces Wipac Part Number S3536 BSA Bantam D7 Coil Ignition 1963-1966 Main Harness